

# Oil Field Environmental Incident Summary

**Incident:** 20140404165656 **Date/Time of Notice:** 04/04/2014 16:56

**Responsible Party:** WPX ENERGY WILLISTON, LLC

**Well Operator:** WPX ENERGY WILLISTON, LLC

**Well Name:** ALFRED OLD DOG 30-31 HC

**Field Name:** REUNION BAY

**Well File #:** 26149

**Date Incident:** 3/4/2014 **Time Incident:** 04:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 150

**Rng:** 93

**Sec:** 30

**Qtr:**

**Location Description:**

**Submitted By:** Jason Rauen

**Received By:**

**Contact Person:** Jason Rauen  
1801 Burdick Expressway West  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	350	Barrels	349.5	Barrels	350	barrels

**Description of Other Released Contaminant:**

Oil based Invert (Drilling Mud)

**Inspected:**

**Written Report Received:** 1/13/2016

**Clean Up Concluded:** 7/4/2014

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

No water was impacted or threatened to be impacted. No equipment was damaged and no personal injury occurred as a result of this incident. Impacts were limited to containment and small area of well pad.

**Action Taken or Planned:**

Pump on-site immediately recovered fluid from containment and returned to upright tank. Small impacts outside of containment were cleaned up by personnel on-site and added to mixing bin of drilling rig. Personnel coached that all cam-locks must be double checked before opening valve and secondary mechanism applied to secure (e.g. bandin or taping of tabs in locked position. Reviewed requirement of personnel to monitor fluid management operations at all times to ensure any release is quickly stopped.

**Wastes Disposal Location:** At an approved facility-Prairie Disposal

**Agencies Involved:** MHA, BIA, BLM

**Updates**

---

**Date:** 4/4/2014      **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release of oil-based mud remained on location within the diking, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.